

25X1A

30 NOV 60

CLASSIFICATION MESSAGE

ORIG :
 UNIT : DPD/DB
 EXT : 8813
 DATE : 30 NOVEMBER 1960

CH/OPS BR
 SECRET

ROUTING	
1	DPD/DB 030109-6
2	C/DPD/DB 5 ACH/DPD
3	C/DPD/DB 6 DPD/RT

TO : 25X1A

FROM: DIRECTOR

CONF: DPD (1,2,3,4,5,6,7,8,9,10)

INFO : S/C (11)

DHD

TOR: 2246Z 30 NOV 60

TO (PRIORITY) 25X1A INFO

25X1A

25X1A FORWARDING INFORMATION ON MISSION G3003 OF CONCERN TO YOU:

RE SIDE SHOWS A DE-SENSITIZED SPOT 2 AND 5/16 INCHES IN FROM DATA CHAMBER EDGE 25X1A AND APPEARS AT SAME FREQUENCY LONGITUDINALLY. BELIEVES THIS IS CAUSED BY APPROXIMATELY .74 A CAMERA ROLLER WITH A DIAMETER OF APPROXIMATELY .74 INCHES. NINE INSTANCES OF SHUTTER MALFUNCTION IN FIRST 75 FRAMES AND ANOTHER INSTANCE AT ABOUT FRAME 150. VACUUM TROUBLE WAS NOTICEABLE BUT NOT TOO SERIOUS, RESOLUTION FAIR. DATA CHAMBER NOT AS LEGIBLE AS USUAL. EXPOSURE ADEQUATE, NO CHANGE ADVOCATED.

END OF MESSAGE

DPD/OPS WAS

This document contains information
 referring to Project CORONA

25X1A

C/DB/DPD

RELEASING OFFICER

COORDINATING OFFICERS

SECRET

MAJOR

USAF

AUTHENTICATING OFFICER

Copy No.

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED